

Digital Indicators 1075 R













Features

Functions:

ON/OFF RESET (Set display to zero) mm/inch Reversal of counting direction PRESET (for entering a numerical value) DATA (data transmission with a data connection cable) LOCK-Function: Individual buttons can be locked Auto-OFF (selectable)

- Immediate measurement due to the Reference system
- Max measuring speed 1.5 m/sec (60"/sec)
- MarConnect Data output: choose either USB OPTO RS232C Digimatic
- High contrast Liquid Crystal Display with 12 mm high digits
- Operating temperature 10-40°C
- Class of protection IP52 according to IEC 60529

Scope of supply: Battery, Operating instructions

4336030

Reference System - Just set once to zero

The new Digital Indicators 1075 R are equipped with the innovative Reference-System. The zero position only has to be set one time: once it is set, the zero remains stored for all further measurements. Therefore, when the indicator is switched ON or the measuring spindle is moved the indicator is immediately ready for measurement; thus the need to reset as with a conventional indicator is now obsolete.

0.001 / **.00005**"

Technical Data							
Measuring range		Resolution		Span of error G *	Measuring force	Weight	Order no.
mm	(inch)	mm	/ inch	mm	N	g	
12.5	(.5")	0.01	/ .0005 "	0.020	0.5 - 1	180	4336010
125	(5")	0.005	/ 0001"	0.015	05 - 1	180	4336020

0.005

(.5")

12.5

^{*} in any zero point